



















Kumodes KM054 montāžas instrukcija



 A	 B	 C	 D Ø3,5×15
 E Ø5×11	 F	 G	 H
 J Ø7×50	 K Ø3×20	 L	 M
 N	 P	 R	 S
	 T	 U	 V



1




2

KM054.1

KM054.3

KM054.2


KM054.4




3


KM054.12

KM054.11







5




6




7



8



9



10

